Qty:

1 Um:

Each

: BASKET BASE ASSEMBLY (350)

: D2221

: N/A

: F/B1 :WIA

: 4/5/2006

: D2221/D2235

Wednesday, 3/29/2006 1:07:16 PM

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

mer Number دُ : CU-DAR001 Dart Helicopters Services

stimate Number

: 26391A

: 10189

P.O. Number

:NIA

This Issue Prsht Rev : 3/29/2006

: NIA

: 26390A

: LARGE FAB ASSY Type

S.O. No. : NIA

COMMENT Relow

Checked & Approved By

Comment

First Issue

Written By

Previous Run

: Est Rev:J 05.09.02

Added D3442-1KJ/JLM

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 D31661

Basket Hoop

Comment: Qty.: 4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

Qty Part Number

4 D3166-1

Description Batch RIB <u>BZ625</u>9

Basket Hinge

CPL 06.04.09

2.0 D22323

Comment: Qty.:

2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Pick:

Qty Part Number

Description _Batch

2 D2232-3 Hinge bracket <u>B25239</u>

CPL 06.04.10

3.0

D2325

Support Gusset (350 Bask



Comment: Qty.:

4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

Qty Part Number

Description

4 D2325 Support Gusset

CPL 06.04.10

4.0

D23273

Spacer Bushing



2.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Pick:

Comment: Qty.:

Qty Part Number

Description

2 D2327-3 Bushing

B25873

CPC 06.04.10

Dart Ae	rospace L	td							
W/O:			W	ORK ORDER CHANGES				· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		**							
						·			
Part No	•	PAR #:	Fault Cat	egory: N	CR: Yes	No DQ	A:	_ Date: _	
					QA: N	I/C Close	d:	_ Date: _	
NCR:		\	NORK ORE	DER NON-CONFORMANC	CE (NCF	₹)			
		Description of NC		Corrective Action Section B		Verific	cation	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	Section C		
								-	
				•					

NOTE: Date & initial all entries

Date: Wednesday, 3/29/2006 1:07:16 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001. Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 26391A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation: Description:** 5.0 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: Description Batch H26204 **Qty Part Number** CPC 06.04.1) Mounting Bracket 2 D2581 6.0 D34421 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description 2 D3442-1 Shim PC 06.04.10 7.0 M304EX07516F Expanded Metal Flat Stai Comment: Qtv.: 39.6900 sf(s)/Unit Total: 39.6900 sf(s) Pick: **Qty Part Number** Description Batch CPC 06.04/1 36 sf M304EX0.75-16F Expanded Metal M304TS0750W065 Comment: Qty.: CPC 06-04-10 29.4000 f(s)/Unit Total: 29.4000 f(s) Pick: Batch: M1000Z3 \rightarrow 93,01" $M100282 \rightarrow 51$ " 9.0 LARGE FAB 1 **Comment: LARGE FABRICATION RESOURCE 1** CPC 06.04.24 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding

5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							·				
Part No	:PAR #:		Fault Category:	NCR: Ye	NCR: Yes No DQA: DQA: QA: N/C Closed:			Date: <u>06/05/04</u>			
				QA	: N/C Close	d:	Date: _				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC		Verification	A	A				
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		

NOTE: Date & initial all entries

Date: Wednesday, 3/29/2006 1:07:16 PM User: Linda Lacelle **Process Sheet** Drawing Name: BASKET BASE ASSEMBLY (350) Customer: CU-DAR001 Dart Helicopters Services Job Number: 26391A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation: Description:** DDIMENSIONAL & WELDING INSPECTION QC9/6 10.0 Comment: DDIMENSIONAL & WELDING INSPECTION POWDER COATING 11.0 POWDER COATING **Comment: POWDER COATING** Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 12.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Seal support gusset seam with white sikaflex-291 Batch: H106 470 Expiry date: __ DOCUMENT CONTROL 14.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion

Dart Aerospace Ltd

Dail Ac	ospace	Liu							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				\					
-						-			
Part No:		PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	_ Date: _	
					QA: N	N/C Close	d:	_ Date: _	
NCR:		\	NORK ORDE	R NON-CONFORMA	NCE (NC	₹)			· · · · · · · · · · · · · · · · · · ·
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verifica		Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
		·					,		
•									

NOTE: Date & initial all entries